


RD 1614 Superintendent's Report
March 2025

3/31//2025

The month of March 2025 was a relatively wet month with rain showers throughout the month. Nevertheless, continued preventative and predictive maintenance was performed on the District's 11 pump stations and levee system. There were no significant problems with pumps or control systems to report. Usually spring time grasses and weeds are beginning to grow excessively, I will be working with a contractor to maintain the grounds.

I met with Jack Wilbur on 2 occasions to plan and design a level gauge system with remote telemetry. I have also been working with Raco alarm systems to determine the best method to be used to send data from the designated pump station to a web based internet site for viewing staff gauge level readings remotely. Below is a basic concept of the design of the staff gauge with telemetry.

Levee inspections: A preliminary inspection was made of the levee system. There are no issues to report. An inspection report is attached..



This concludes my report, Respectfully:

Abel Palacio - Reclamation District 1614 Superintendent

Reclamation District 1614 Monthly Waterside Inspection Report (With RD 828 Observations)

Personnel present: Abel Palacio (RD 1614 Superintendent), Aaron Lickingteller (KSN)

Inspection conducted: Tuesday, March 25, 2025 at 8:30am –12:30pm. Low tide occurred at 11:12am (-0.1 feet) and high tide occurred at 3:05pm (3.6 feet). The following points of interest were observed during the inspection:

Photos of Smith Tract



1448 W. South Tuxedo Ave.: Dense overgrowth renders the levee slope invisible.



1466 W. South Tuxedo Ave.: More dense vegetative overgrowth on the levee slope.



1510 W. South Tuxedo Ave.: The dock is slowly degrading with time.



1534 W. South Tuxedo Ave.: Yet more dense vegetation on the levee slope making inspection impossible.



1722 W. South Tuxedo Ave.: Old rock slipping down the waterside slope



1742 W. South Tuxedo Ave.: The lady who claims the Reclamation District does not exist resides here.



1822 W. South Tuxedo Ave.: Owner approved RSP placement in the near future.



1826 W. South Tuxedo Ave.: Owner approved RSP placement in the near future.



1842 W. South Tuxedo Ave.: The property immediately east of the condemned address (1848 W.S. Tuxedo Ave.) has dense waterside slope vegetation making inspection impossible.



1848 W. South Tuxedo Ave.: This property has been condemned by the City of Stockton and all appeals by the property owner have been exhausted.



2000 Mission Rd.: A sunken boat bobs along in the canal at this location.



2024 Idaho Ave.: Dense waterside slope vegetation renders the levee impossible to inspect.



3014 Canal Dr.: A good candidate for RSP.



3028 Canal Dr.: Another good candidate for RSP.



3042 Canal Dr.: Yet another good candidate for RSP.